



PRODUCT SUPPORT.....SERVICE NEWS

BULLETIN NO.: 2002-031	DATE: Dec. 15, 2002	PAGE: 1 of 1
TITLE: Parts Catalog Correction, Engine Room Keys	RELEASE: Dealer/Customer	
SECTION: General	MODEL: 65~90ZV	

GENERAL:

The purpose of this Service News is to correct the engine housing lock insert description in the parts catalog and provide the correct part number for the starter and engine housing key.

DETAIL:

In many of the parts catalogs for 65~90ZV, you may find on page 128-1 and 128-2 item 23 that has a part number 32110-60010, and a description of "Key". This is incorrect. This part number actually is for a lock insert assembly.

The engine housing key part number is 32110-70170.

Please use the correct part number when ordering these parts.